

ADJUSTMENT OF TOBY OIL CONTROL



Point A is adjustment of the small flame.

It says + and – by the adjustment screws, so it should not be difficult.

The correct adjustment is when the flame in the burner burns all the way round seen through the inspection hole in the lid.

Point B is adjustment of the big flame.

The screws is also here marked with + and -.

The max flame must not be so high that the stove and the exhaust pipe get red glowing.